

**Program Year 2005 90TLR Models**  
**FACTORY MODIFICATION CAMPAIGN – Loose Mounting Bolts**  
**Yamaha Technical Bulletin O2007-001R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, USA has decided that a possible defect relating to safety may exist in certain program-year 2005 90TLR (90 horsepower) outboard motors.

**Affected Models**

Check the affected Primary Identification Number range carefully. Units outside this limited range are not affected.

Model	PID Number range
90TLR	6H1L-1021736~1022035

**The reason for this recall:** In the affected units, there is a potential for the oil pump mounting bolts to be loose. If this occurs, the throttle link rod might catch on these loose bolts, which could cause the throttle valve to stick in an open position. This could result in loss of control and an accident with injury or death.

**What Yamaha and your dealer will do:** To correct this defect, Yamaha is initiating a Factory Modification Campaign. Affected outboard motors must have the oil pump mounting bolts tightened securely. There will be no charge to you for this procedure.

**What you should do now:** Do not operate your outboard motor until this important modification is performed.

If you are not the first owner of the outboard motor, and are unsure if this modification has been done, contact any authorized Yamaha Marine Dealer to check. Any authorized Yamaha Marine Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.