Program Year 2007 F15 and F20 Tiller Handle Models FACTORY MODIFICATION CAMPAIGN – Tiller Handle Assembly Yamaha Technical Bulletin O2007-005R

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided that a possible defect relating to safety may exist in certain program-year 2007 F15CELH/ CESH/ CMLH/ CMSH/ CPLH and F20ELH/ ESH/ MLH/ MSH/ PLH tiller-handle model outboard motors.

Affected Models

Check the affected Primary Identification Number range carefully. Units outside this limited range are not affected.

Model	PID Number range
F15CELH	6AGKL-1000106~1003991
F15CESH	6AGKS-1000020~1003981
F15CMLH	6AGKL-1000060~1003716
F15CMSH	6AGKS-1000001~1003844
F15CPLH	6AGKL-1000121~1004024
F20ELH	6AHKL-1000208~1006081
F20ESH	6AHKS-1000022~1006067
F20MLH	6AHKL-1000137~1005969
F20MSH	6AHKS-1000072~1005597
F20PLH	

The reason for this recall: In the affected units, there is a potential for the grip's throttle shaft on the tiller (steering) handle to break. This could cause loss of throttle control and reduced steering ability, which could result in loss of control and an accident with injury or death.

What Yamaha and your dealer will do: To correct this defect, Yamaha is initiating a Factory Modification Campaign. Affected outboard motors must have the tiller handle assembly replaced with one of a new design. There will be no charge to you for this procedure.

What you should do now: Do not operate your outboard motor until this important modification is performed.

If you are not the first owner of the outboard motor, and are unsure if this modification has been done, contact any authorized Yamaha Marine Dealer to check. Any authorized Yamaha Marine Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.