



YAMAHA MOTOR CORPORATION, U.S.A. 6555 Katella Avenue, Cypress, CA 90630-5101 866-894-1626

IMPORTANT SAFETY RECALL NOTICE

April 5, 2017

This notice applies to your outboard motor (serial number XXXX-XXXXXXX).

Model: F90B

Campaign 990113

Dear Yamaha Owner:

Yamaha Motor Corporation, U.S.A. has decided that a defect that relates to safety may exist in certain program-year 2017 F90LB and F90XB outboard motors. Our records indicate that you own the affected outboard motor shown above.

The reason for this recall:

In affected units, there is the potential for the bushing at the end of the throttle control lever to have been incorrectly installed during factory assembly, allowing the bushing to become loose and possibly catch on the accelerator cam guide. In the worst case, this may result in loss of engine speed control, which could cause loss of control and an accident with injury or death.

What Yamaha and your dealer will do:

To correct this defect, your authorized Yamaha dealer will install a new throttle control lever bushing. The procedure takes about one hour and 15 minutes to perform, but your dealer may need to keep your outboard longer. There will be no charge to you for this procedure.

What you should do now:

Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your outboard to complete this service. Remember to take this letter with you when you take in your outboard.

You should not operate your affected outboard shown above until this modification is performed.

If you are unable to return to the Yamaha dealer who sold you the outboard, this service will be performed by any authorized Yamaha Outboard dealer. To find a dealer near you, call 1-800-88-YAMAHA or visit the Yamaha website at www.yamahaoutboards.com.

If you have had this repair performed before you received this letter, you may be entitled to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this repair. For more information, contact Yamaha Outboard Customer Relations at 1-866-894-1626.

If you need help:

If, after contacting your dealership, you have questions or concerns which the dealership is unable to answer, please write to:

Yamaha Motor Corporation, U.S.A.
Outboard Customer Relations Department
1270 Chastain Road
Kennesaw, GA 30144

Or call: 1-866-894-1626

If you no longer own this Yamaha:

If you have sold your outboard to another party, please call us toll-free at 1-866-894-1626 with the name and address of the new owner, along with the Primary ID number shown above your name on this letter.

We're sorry to cause you any inconvenience, but we are sincerely concerned about your safety and continued satisfaction with our products. Thank you for giving your attention to this important matter.

Sincerely,
Yamaha Marine Service
Yamaha Motor Corporation, U.S.A.